

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R00050008013273

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 2-9-57

P.O. NO.

VENDOR PACKING SLIP NO.

BUY OUT CODE NO.

O ACCT. OR

R W.O. NO.

S.O. NO.

FLAT #

CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED OR STANDARD PART NO.	DWG. REV.	COT. NO.	CLASS NUMBER	OPER. NUMBER	QUANTITY	REMARKS
CHARGE TO	QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION				ACCEPTED	REJECTED	
	322	732180 Shaft Asby		63	3	22	2	
		SHAFTRN #305922						

RECEIVED BY *Johns* INSPECTED BY *Aud* DATE *2/12/57* PROJECTS RETURNED ON SHIP. MEMO NO.

HMC-1058

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11230

RECEIVED FROM

DATE REC'D. 2-9-57

P.O. NO. 45724

VENDOR PACKING SLIP NO. 25517

BUY OUT CODE NO.

O ACCT. OR

R W.O. NO.

S.O. NO.

Bearing Service Inc. Norwood, California

CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED OR STANDARD PART NO.	DWG. REV.	COT. NO.	CLASS NUMBER	OPER. NUMBER	QUANTITY	REMARKS
CHARGE TO	QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION				ACCEPTED	REJECTED	
	322	920006		7C	3	22	10	
		730170-008 bearing, ball <i>70055</i> New Departure						

RECEIVED BY *Johns* INSPECTED BY *Aud* DATE *2/14/57* PROJECTS RETURNED ON SHIP. MEMO NO.

HMC-1058

Approved For Release 2000/04/18 : CIA-RDP81B00879R00050008013273